



INSERT BETWEEN
PINS 8 AND 9.

SEE NOTES

SEE NOTES

NOTES:

1. USE THE TWO SCREWS, F, TO FASTEN THE CONNECTOR, 60326, TO THE BACK OF THE UNIT.
2. THE TWO SPACERS, H, MAY BE USED WITH THE TWO SCREWS, F, TO FASTEN THE CONNECTOR, 60326, TO THE BACK OF THE UNIT WHEN THE UNIT HAS BEEN PLACED IN A PANEL.

PARTS LIST

SYM	QTY	PART #	NAME
A	1	25131	CONNECTOR, 20 PIN SOLDER EYELET
B	1	25139	POLARIZING KEY
C	2	71351	S/M, 3000/9000 CLAMP BAR
D	2	72225	F/S/M, 3000 CONNECTOR SHELL
E	4	80012	SCREW, 4-40 x .500 BHMS
F	2	80013	SCREW, 4-40 x .625 PHMS
G	4	80135	SCREW, 4-40 x .187 FHMS
H	2	87052	SPACER, .115x.156x.25 ROUND
J	2	87076	STANDOFF, 4-40 x .188SQ x .344L

PROPRIETARY INFORMATION

THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF DAYTRONIC CORPORATION, AND REMAINS THE PROPERTY OF DAYTRONIC CORPORATION. NEITHER THIS DOCUMENT NOR THE INFORMATION CONTAINED HEREIN MAY BE REPRODUCED, USED OR DISCLOSED TO ANY THIRD PARTY WITHOUT THE EXPRESS WRITTEN CONSENT OF DAYTRONIC CORPORATION.

© DAYTRONIC 1998

CSR	A	12-9-98	ECD 15295		
DFT.	REV.	DATE	DESCRIPTION	APP.	
CW	DES.	CHK	 DAYTRONIC CORPORATION DAYTON, OHIO		
CSR	DFT.	APP.			
DATE:	12-9-98	REV.		REV. LEVEL:	A
NAME	60326 ASSEMBLY INSTRUCTIONS			NUMBER	96005